


K&A Manufacturing  
6703 Zinser Street Schofield, WI 54476  
Phone: 800.298.4351  
Fax: 866.882.9475  
www.raproducts.com



### **Operation and Reset Procedure**

**Plug the power cord into a standard 110v receptacle. A power surge protector is recommended. Press the down arrow until the worksurface reaches its lowest position and the control box beeps (3) times. The NewHeights workstation is ready for use.**

**Reset Procedure:** Unplug the power for 30 seconds. Hold the down arrow until the unit stops at the bottom and the control box beeps (3) times.

**Troubleshooting:** If you are having any problems with the table operation, contact RightAngle™ service at 800-298-4351 or [orders@raproducts.com](mailto:orders@raproducts.com).