



### **Operation and Reset Procedure**

Plug the power cord into a standard 110v receptacle. A power surge protector is recommended. Press the down arrow until the worksurface reaches its lowest position and clicks. The NewHeights<sup>™</sup> workstation is ready for use.

**Reset Procedure:** Unplug the power for 30 seconds. Hold the down arrow button until the unit stops at the bottom. Release the button; then hold the down arrow button until the unit clicks twice.

**Troubleshooting:** If you are having any problems with the table operation, contact RightAngle<sup>™</sup> service at 800-298-4351 or [orders@raproducts.com](mailto:orders@raproducts.com).